SEAM CLEANER





FiberTite Seam Cleaner to be used to clean membrane seams prior to welding.

DESCRIPTION

FiberTite Seam Cleaner is to be used with clean white cotton cloths/rags to clean contamination from the seam areas of the membrane prior to welding. Wearing all personal protective equipment, including protective eye wear and gloves, pour the seam cleaner onto the clean white cotton rag and wipe the wet rag along the area to be cleaned.

DO NOT POUR THE SEAM CLEANER DIRECTLY ON THE MEMBRANE.

After cleaning, allow the seam area to completely dry before initiating the welding process. The cleaner is not to be used to clean areas of exposed membrane.

FiberTite Seam Cleaner is only necessary when the seam area is contaminated with dirt or other foreign material. For heavily soiled membrane, it is recommended that the area be cleaned first with a detergent, rinsed clean, dried and then cleaned with FiberTite Seam Cleaner prior to welding.

Store the FiberTite Seam Cleaner in a cool / dry location at temperatures between 40°F (4°C) and 80°F (27°C). Review the FiberTite Seam Cleaner Safety Data Sheet (SDS) and follow all the safety precautions contained therein.

PHYSICAL PROPERTIES	
Composition	Colorless Liquid
Shelf Life	12 months
Vapor Density	Heavier than air
VOC Content	0 g/l per exemption The U.S. EPA, SCAQMD and other agencies consider the solvent in the FiberTite Seam Cleaner to be exempt and therefore the VOC content can be considered "0 g/l".



For more information on FiberTite Systems and accessories please call: Seaman Corporation (800) 927-8578 International (330) 262-1111 www.fibertite.com

FiberTite® is a registered trademark of Seaman Corporation.





